L	Type	# 17	Hits	Search Text	DBs	Time Stamp C	Comments	Error Definition	Erro
	BRS	1241	800	USPAT; US-PGPU B; EPO; (ceramic near package) same metal JPO; j IBM TDB	USPAT; US-PGFU B; EPO; JPO; DERWENT ; IBM	2001/12/20 16:40			0
<u> </u>	BRS	L242	2829	kv same metal	D . E	2001/12/20 16:40			0
<u> </u>	BRS	L243	64	kv near metal	D 1. H	2001/12/20 16:43	×		0
	BRS	L244	1750	"42" near alloy	D •• E	2001/12/20 17:34			0
 	BRS	L245	610	1244 and ceramic		2001/12/20 16.55			0
T	BRS	L246	525	L245 and metal	D E	2001/12/20			0
	BRS	1247	0	koval near kv	D . T	2001/12/20 17:31			0
	BRS	L248	2829	metal same kv	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/20 16:59			0

	Type	#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Erro
0	BRS	L249	80	L248 and 257/\$.ccls.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/12/20 17:13		-	O
10	IS&R	L250	П	("6316826").PN.	i	2001/12/20 17:24			0
11	BRS	L251	23	1244 and kv		2001/12/20 17:25			0
12	BRS	1252	2	kovar near kv	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/12/20 17:32			0
13	BRS	1254	28836	L and molybdenum		2001/12/20 17:37			0
14	BRS	1255	99	L253 and molybdenum		2001/12/20 17:39			0
15	BRS	1256	35	L253 and (copper with molybdenum)	USPAT; US-PGPU B; EPO; JPO; DERWENT; IBM	2001/12/20 17:40		4	0
16	BRS	1.253	301	("42" near alloy) with Kovar	D E :	2001/12/20 18:24			0
17	BRS	L257	169	253 and ceramic	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/20 18:28			0